

February 8, 2018

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

Branch	Model	Brand	Description		QTY	Price Each
3921	186BNA024000	Bryant AC	16S Evolution 1 stg 2T	Lite cabinet damage	1	849.00
3950	BA13NA018BNG	Bryant AC	13S Sentry 1.5T	Lite cabinet damage	3	679.00
3950	BA13NA0240NG	Bryant AC	13S 2T	Coil rub mark	1	699.00
3950	BA14NA02400G	Bryant AC	14A 2T	Lite/med cabinet damage	1	699.00
3910	315AAV066135	Bryant Furnace	Plus 80V 2stg VS 4way	Dent to base of unit	1	895.00
3920	915SA30040S14	Bryant Furnace	95% Single Stage	Med cabinet damage	1	800.00
3933	24ABB330A005	Carrier AC	13S Comfort P 2.5T 3 phase	Very minor cabinet dent	1	729.00
3910	24ABB360A006	Carrier AC	13S Comfort P 5T 460-3	Med cabinet damage	1	999.00
3930	24ABB360A006	Carrier AC	13S Comfort P 5T 460-3	Lite cabinet damage	1	1,149.00
3930	CA14NA04800G	Carrier AC	13S Sentry 4T	Lite cabinet damage	1	799.00
3933	CA16NA06000G	Carrier AC	16S Sentry 5T	Lite cabinet damage	1	899.00
3920	CA16NW01800G	Carrier AC	16S Sentry 1.5T	Lite cabinet damage	1	699.00
3920	CA16NW02400G	Carrier AC	16S Sentry 2T	Lite cabinet damage	2	710.00
3910	58CTW110---1--22	Carrier Furnace	80% 4way 2 stage PWM	Lite/med cabinet damage	1	679.00
3934	59TP6A120E24--22	Carrier Furnace	96% AFUE 2S/PWM	Med cabinet damage	1	1,250.00
3930	25HNB648A003	Carrier HP	16S Infinity 4T P	Lite cabinet damage	1	2,210.00
3950	25VNA036A003	Carrier HP	3T Inverter	Med cabinet damage	1	3,235.00
3930	25VNA824A003	Carrier HP	Infinity 18 Seer VS 2T	Lite cabinet damage	1	2,225.00
3930	25VNA860A003	Carrier HP	Infinity 18 Seer 5T	Med cabinet damage	1	2,975.00
3940	CH14NB02400G	Carrier HP	14S Sentry 2T	Lite/med cabinet damage	1	829.00
3930	CH14NB03600G	Carrier HP	14S Sentry 3T	Lite cabinet damage	1	1,110.00
3930	38GRQB18---3	DLS	27 Seer 18K CDU	Lite/med cabinet damage	2	799.00
3930	38MBQB36---3	DLS	18S 36K HP DCU	Lite cabinet damage	1	1,229.00
3920	40MKCB54F--3	DLS	54K 230V IDU under ceiling	Lite cabinet damage	2	829.00
3940	FE4ANF005L00	Fan Coil	4T VS Alum	Med cabinet damage	1	999.00
3910	FB4CNP024L00	Fan Coil	2T Alum	Lite cabinet damage	1	359.00
3920	FB4CNP025L00	Fan Coil	2T Alum	Lite/med cabinet damage	4	365.00
3910	FB4CNP061L00	Fan Coil	Alum 5T	Bottom dent med	1	899.00
3930	FV4CNF002L00	Fan Coil	Alum VS 2T	Lite cabinet damage	1	699.00
3920	FV4CNF003L00	Fan Coil	VSP alum 3T	Lite cabinet damage	1	829.00
3940	FV4CNF003L00	Fan Coil	VSP alum 3T	Lite cabinet damage	1	829.00
3930	FX4DNF037L00	Fan Coil	Alum 3T	Lite cabinet damage	1	699.00
3934	FX4DNF043L00	Fan Coil	3T Alum	Med cabinet damage	1	799.00
3930	END4X48L24A	ICP Evap Coil	Vertical 4T	Lite/med cabinet damage	1	349.00
3930	PA13NA048BNG	Payne AC	13A 4T	Lite cabinet damage	1	699.00
3910	PH15NB01800G	Payne HP	15S DG 1.5T	Small dent left side	1	629.00