

February 27, 2018

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 [rwiebelhaus@comfortproducts.com](mailto:rwiebelhaus@comfortproducts.com)

| Branch | Model            |    | Brand           | Description                |                              | QTY | Price Each |
|--------|------------------|----|-----------------|----------------------------|------------------------------|-----|------------|
| 3910   | CEV4821E35       | 1W | ADP Evap Coil   | 3.5-4T Vert A Coil w/o txv | <b>SOLD</b>                  | 1   | 210.00     |
| 3934   | CEV4821E35       | 3C | ADP Evap Coil   | 3.5-4T Vert A Coil w/o txv | Dent in side coil is fine    | 1   | 210.00     |
| 3921   | 186BNA024000     | 1W | Bryant AC       | 16S Evolution 1 stg 2T     | <b>SOLD</b>                  | 1   | 809.00     |
| 3950   | BA13NA0240NG     | DC | Bryant AC       | 13S 2T                     | Coil rub mark                | 1   | 689.00     |
| 3950   | BA14NA02400G     | 2F | Bryant AC       | 14A 2T                     | Lite/med cabinet damage      | 1   | 689.00     |
| 3910   | 315AAV066135     | FC | Bryant Furnace  | Plus 80V 2stg VS 4way      | Dent to base of unit         | 1   | 845.00     |
| b3920  | 915SA30040S14    | 2C | Bryant Furnace  | 95% Single Stage           | Med cabinet damage           | 1   | 789.00     |
| 3933   | 24ABB330A005     | 1C | Carrier AC      | 13S Comfort P 2.5T 3 phase | Very minor cabinet dent      | 1   | 699.00     |
| 3910   | 24ABB360A006     | 3W | Carrier AC      | 13S Comfort P 5T 460-3     | <b>SOLD</b>                  | 1   | 945.00     |
| 3930   | 24ABB360A006     | 1W | Carrier AC      | 13S Comfort P 5T 460-3     | Lite cabinet damage          | 1   | 1,109.00   |
| 3930   | CA14NA04800G     | 1W | Carrier AC      | 13S Sentry 4T              | Lite cabinet damage          | 1   | 779.00     |
| 3920   | CA16NW01800G     | 2F | Carrier AC      | 16S Sentry 1.5T            | Lite cabinet damage          | 1   | 679.00     |
| 3920   | CA16NW02400G     | 2F | Carrier AC      | 16S Sentry 2T              | <b>SOLD</b>                  | 1   | 799.00     |
| 3910   | 58CTW110---1--22 | 2C | Carrier Furnace | 80% 4way 2 stage PWM       | Lite/med cabinet damage      | 1   | 669.00     |
| 3910   | 58CVA135---1--22 | 2C | Carrier Furnace | 80% 2 Stg VS 4way MP       | Cabinet damage lite to med   | 1   | 1,249.00   |
| 3910   | 59SC2C040S17--12 | 1W | Carrier Furnace | 92% SS GASF All Flow       | Scratches only               | 1   | 799.00     |
| 3940   | 59TP6A080E17-16  | 2W | Carrier Furnace | 96% AFUE 2S/PWM            | <b>SOLD</b>                  | 1   | 1,260.00   |
| 3934   | 59TP6A120E24--22 | 2C | Carrier Furnace | 96% AFUE 2S/PWM            | <b>SOLD</b>                  | 1   | 1,199.00   |
| 3930   | 25HNB648A003     | 1W | Carrier HP      | 16S Infinity 4T P          | <b>SOLD</b>                  | 1   | 2,199.00   |
| 3920   | 25VNA024A003     | 2W | Carrier HP      | Inverter 2T                | Base damage                  | 1   | 2700.00    |
| 3950   | 25VNA036A003     | 2C | Carrier HP      | 3T Inverter                | Med cabinet damage           | 1   | 3,235.00   |
| 3930   | 25VNA824B003     | 1C | Carrier HP      | Infinity 18 Seer VS 2T     | <b>SOLD</b>                  | 1   | 2,099.00   |
| 3930   | 25VNA860A003     | 2W | Carrier HP      | Infinity 18 Seer 5T        | Med cabinet damage           | 1   | 2,875.00   |
| 3940   | CH14NB02400G     | 2C | Carrier HP      | 14S Sentry 2T              | <b>SOLD</b>                  | 1   | 799.00     |
| 3940   | 38MAQB12R--3     | 2C | DLS             | 24S 12K 230V HP CDU        | <b>SOLD</b>                  | 1   | 499.00     |
| 3930   | 38GRQB18---3     | 2W | DLS             | 27 Seer 18K CDU            | Lite/med cabinet damage      | 1   | 779.00     |
| 3930   | 38MBQB36---3     | 1W | DLS             | 18S 36K HP DCU             | Lite cabinet damage          | 1   | 1,099.00   |
| 3920   | 40MKCB54F--3     | 2w | DLS             | 54K 230V IDU under ceiling | Lite cabinet damage          | 2   | 799.00     |
| 3951   | CNPVP4221ALA     | 2F | Evap Coil       | 3.5T                       | <b>SOLD</b>                  | 1   | 299.00     |
| 3934   | FB4CNF036L00     | 3C | Fan Coil        | 3T Alum                    | Dent in front door not major | 1   | 547.00     |
| 3910   | FB4CNP018L00     | 3W | Fan Coil        | Alum 1.5T                  | <b>SOLD</b>                  | 1   | 449.00     |
| 3920   | FB4CNP025L00     | 2C | Fan Coil        | 2T Alum                    | Lite/med cabinet damage      | 1   | 355.00     |
| 3910   | FB4CNP061L00     | 3C | Fan Coil        | 1.5T Alum                  | Lite damage base front       | 1   | 1,237.00   |
| 3940   | FE4ANF005L00     | 2W | Fan Coil        | 4T VS Alum                 | <b>SOLD</b>                  | 1   | 979.00     |
| 3930   | FV4CNF002L00     | 2F | Fan Coil        | Alum VS 2T                 | Lite cabinet damage          | 1   | 679.00     |
| 3920   | FV4CNF003L00     | 2F | Fan Coil        | VSP alum 3T                | Lite cabinet damage          | 1   | 799.00     |
| 3940   | FV4CNF003L00     | 2W | Fan Coil        | VSP alum 3T                | Lite cabinet damage          | 1   | 799.00     |
| 3930   | FX4DNF037L00     | 1W | Fan Coil        | Alum 3T                    | Lite cabinet damage          | 1   | 679.00     |
| 3934   | FX4DNF043L00     | 2C | Fan Coil        | 3T Alum                    | Med cabinet damage           | 1   | 779.00     |
| 3930   | END4X48L24A      | 2W | ICP Evap Coil   | Vertical 4T                | Lite/med cabinet damage      | 1   | 339.00     |
| 3930   | PA13NA048BNG     | 1W | Payne AC        | 13A 4T                     | Lite cabinet damage          | 1   | 679.00     |
| 3934   | PG8MAA036110     | 3C | Payne Furnace   | 4 way 80%                  | Front top corner dent        | 1   | 411.00     |
| 3934   | PG8MAA048110     | 3C | Payne Furnace   | 4 Way 80%                  | Back dent cosmetic           | 1   | 445.00     |
| 3910   | PH15NB01800G     | 2F | Payne HP        | 15S DG 1.5T                | <b>SOLD</b>                  | 1   | 609.00     |
| 3910   | P110-LBP2417     | 2F | Totaline        | Humidifier Bypass          | <b>SOLD</b>                  | 1   | 75.00      |