

August 16, 2018

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

Branch	Model	Brand	Description		QTY	Price Each
3952	127ANA060B00	Bryant AC	17S Preferred 2 stg	Small dent top	1	1,941.00
3940	310AAV036110	Bryant Furnace	80% STD 4way Multi	Installed never wired/left return cut out	1	499.00
3933	313ABV060110	Bryant Furnace	80% AFUE SS w/X13	Lite cabinet damage	1	899.00
3910	315AAV066135	Bryant Furnace	Plus 80V 2stg VS 4way	Dent to base of unit	1	749.00
3920	926TA60100V21	Bryant Furnace	96% 4way AFUE 2S/PWM	Base damage very bottom medium	1	999.00
3934	926TA66120V24	Bryant Furnace	96% 4way AFUE 2S/PWM	Back corner damage from top to bottom	1	979.00
3921	987MA42080V17	Bryant Furnace	97% Modulate	Very minor cosmetic	1	1,558.00
3933	24ABB330A005	Carrier AC	13S Comfort P 2.5T 3 phase	Very minor cabinet dent	1	649.00
3910	24ABB336A005	Carrier AC	13S Comfort P 3T 3 Phase	Partially installed no damage	1	879.00
3920	24ABB336A005	Carrier AC	13S Comfort P 3T 3 Phase	corner of grill and rub on coil medium	1	700.00
3910	24ABB342A005	Carrier AC	13S Comfort P 3.5T 3 Phase	Partially installed no damage	1	899.00
3910	24ABB348A005	Carrier AC	13S Comfort P 4T 3 Phase	Partially installed no damage	1	925.00
3910	CA13NA018BNG	Carrier AC	13S Sentry 1.5T	Lite cabinet damage	1	769.00
3951	CA13NA024BNG	Carrier AC	13S Sentry 2T	Leaning compressor lite pan damage	1	400.00
3910	58CTW110---1--22	Carrier Furnace	80% 4way 2 stage PWM	Lite/med cabinet damage	1	659.00
3950	59MN7A060V17--14	Carrier Furnace	97% Modulate	Very minor rear left corner	1	1,572.00
3940	59TN6A100V21--22	Carrier Furnace	96% 2 stg	Slight dent bottom back corner	1	1,589.00
3910	59TP6A080E21--20	Carrier Furnace	96% 4way AFUE 2S/PWM	Top corner small crease	1	950.00
3930	38GRQB18---3	DLS	27 Seer 18K CDU	Lite/med cabinet damage	1	679.00
3930	38MBQB36---3	DLS	18S 36K HP DCU	Lite cabinet damage	1	979.00
3910	40MAQB09B--3	DLS	24S 9K 230V I DU HW	Lite cabinet damage	1	199.00
3920	40MKCB54F--3	DLS	54K 230V IDU under ceiling	Lite cabinet damage	2	699.00
3933	CNPVP4824ALA	Evap Coil	Alum 4T	Minor case damage	1	215.00
3933	FB4CNF018L00	Fan Coil	Alum 1.5T	Blower is crooked	1	250.00
3934	FB4CNP018L00	Fan Coil	Alum 1.5T	Small front corner damage	1	449.00
3940	FB4CNP030L00	Fan Coil	Alum 2T	Previously installed never wired/scratches	1	479.00
3934	FX4DNF043L00	Fan Coil	Alum 3.5T	Lite cabinet damage	1	990.00
3930	END4X48L24A	ICP Evap Coil	Vertical 4T	Lite/med cabinet damage	1	199.00
3910	PG8MAA036110	Payne Furnace	80% 4 way	Lite cabinet damage/corner kink	2	349.00