



Comfort Products Distributing
 13202 I Street
 Omaha, NE 68137
 Ph: 402-334-7777 or 800-779-8299
 comfortproducts.com

June 10, 2019

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

	Model	Brand	Description		QTY	Price Each
3910	113ANA0420N0	Bryant AC	13S 3.5T	Top is slightly rolled over on one side	1	1,050.00
3930	113APA060000	Bryant AC	13S Legacy 5T	Lite/med cabinet damage	1	SOLD
3921	126BNA018000	Bryant AC	16S Preferred 1.5T	Grill Bent/fin damage	1	600.00
3910	987MA66100V21	Bryant Furnace	97% Modulating	Small dent lower side	1	SOLD
3910	214DNA048000	Bryant HP	14S 4T Legacy	Light dent at base pan no coil damage	1	1,585.00
3910	280ANV036000	Bryant HP	3T Inverter	Rail dented no unit damage	1	SOLD
3920	24ABB336A005	Carrier AC	13S Comfort 3T 3phase	Lite/med cabinet damage	1	899.00
3910	CA13BA018BNG	Carrier AC	13S 1.5T	Lite cabinet damage	1	525.00
3910	CA13NA024BNG	Carrier AC	13S 2T DG	Lite pan damage	2	699.00
3910	59MN7A100V21--20	Carrier Furnace	97% AFUE Infinity	Slight twist of cabinet	1	1,400.00
3910	59SC5A080S21--20	Carrier Furnace	95% SS Comfort	dent in door lite cabinet damage	1	SOLD
3933	59TN6A120V24--22	Carrier Furnace	96% 2stg Infinity	Lite/med cabinet damage	1	1,149.00
3910	CH14NB02400G	Carrier HP	14S 2T DG	Scratches in back panel	1	SOLD
3920	CH14NB02400G	Carrier HP	14S 2T DG	Lite cabinet damage	1	SOLD
3910	CH14NB06000G	Carrier HP	14S 5T DG	Base pan damage	1	1,450.00
3920	CH16NA02400G	Carrier HP	16S 2T DG	Base pan bent up in front slight coil rub	1	699.00
3920	CH16NA02400G	Carrier HP	16S 2T DG	Coil has some bent fins (med) no leak	1	599.00
3920	CAPMP3617ALA	Evap Coil	Uncased 3T 17"	Lite/med cabinet damage	1	SOLD
3921	CNPVP1917ALA	Evap Coil	1.5T 17" P	Lite cabinet damage	1	SOLD
3910	CSPHP6012ALA	Evap Coil	Horizontal 5T Slab Coil	Lite cabinet damage	1	SOLD
3910	FB4CNP048L00	Fan Coil	4T Alum	Blower motor fell inside. No outside damage	1	325.00
3910	FB4CNP061L00	Fan Coil	5T ECM TXV	Lite top corner crease	1	1,100.00
3910	FFMANP030T00	Fan Coil	TP 2.5T	Bent blower housing	1	499.00
3921	PA16NW01800G	Payne AC	16S 1.5T DG	Grill slightly pushed in small fin dam	1	949.00
3910	PG8MAA066135	Payne Furnace	80 AFUE 4way	Top corner small tweek	1	555.00