



comfort | excellence
Comfort Products Distributing

Comfort Products Distributing
13202 I Street
Omaha, NE 68137
Ph: 402-334-7777 or 800-779-8299
comfortproducts.com

August 12, 2019

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

	Model	Brand	Description		QTY	Price Each
3921	113ANA018BN0	Bryant AC	13S 1.5T	Small dent in fan deck	1	697.00
3921	113ANA036BN0	Bryant AC	13S 3T	Dented top lite scrap to top edge coil	1	677.00
3921	113ANA036BN0	Bryant AC	13S 3T	Dent top lite scraps to cabinet	1	677.00
3910	113ANA0420N0	Bryant AC	13S 3.5T	Top is slightly rolled over on one side	1	1,050.00
3933	116BNA036000	Bryant AC	16S 3T	Light fin and guard damage	1	1,099.00
3921	126BNA018000	Bryant AC	16S Preferred 1.5T	Grill Bent/fin damage	1	600.00
3934	310AAV048110	Bryant Furnace	80% STD 4way Multi	Dented bottom door and bottom cabinet	1	499.00
3933	313ABV036070	Bryant Furnace	80% 4way AFUE X13	Casing damage on back	1	699.00
3910	915SA42060S17	Bryant Furnace	95% SS GASF	Lite kink to cabinet	1	749.00
3921	915SA42060S17	Bryant Furnace	95% SS GASF	Very light cosmetic damage	1	799.00
3910	214DNA048000	Bryant HP	14S 4T Legacy	Light dent at base pan no coil damage	1	1,585.00
3910	226ANA048000	Bryant HP	4T 2stg Preferred	Installed Small dent lower and front side	1	1,599.00
3920	24ABB336A005	Carrier AC	13S Comfort 3T 3ph	Coil fins smashed on corner	1	800.00
3910	24ABB342A0N3	Carrier AC	13S 3.5T	Dent top	1	899.00
3910	CA13BA018BNG	Carrier AC	13S 1.5T	Base pan bent up in front slight coil rub	1	525.00
3910	CA13NA024BNG	Carrier AC	13S 2T DG	Lite pan damage	1	699.00
3910	CA13NA030BNG	Carrier AC	13S 2.5T DG	Lite base pan and top edge dent	1	570.00
3910	CA13NA030BNG	Carrier AC	13S 2.5T DG	Lite base pan and top edge dent	1	570.00
3934	CA16NW06100G	Carrier AC	16S 5T DG	Light fin damage	1	1,049.00
3933	58STA155---1--20	Carrier Furnace	80 STD 4way Multi	Bottom casing damage wobbly	1	499.00
3910	25HBC524A003	Carrier HP	15S Comfort 2T DG	No box Lite dent top	1	1,249.00
3934	25HBC524A003	Carrier HP	15S Comfort 2T DG	Top damage	1	1,249.00
3933	25HBC548A003	Carrier HP	15S Comfort 4T DG	Fin damage and top	1	1,849.00
3910	CH14NB02400G	Carrier HP	14S 2T DG	No box med coil rub/no leak	1	535.00
3920	CH16NA02400G	Carrier HP	16S 2T DG	Base pan bent up in front slight coil rub	1	699.00
3920	CH16NA02400G	Carrier HP	16S 2T DG	Coil has some bent fins (med) no leak	1	599.00
3910	CAPMP6024ALA	Evap Coil	5T 24"	Pinched corner	1	238.00
3934	CEH3614D12	Evap Coil	3T 14" ADP	Side damage cab only	1	205.00
3934	FB4CNP025L00	Fan Coil	2T Alum	Top corner	1	516.00
3934	PA13NA0360NG	Payne AC	13S 3T DG	Dented coil	1	714.00
3910	PA13NA0600NG	Payne AC	13S 5T DG	Lite base pan and top edge dent	1	899.00
3910	PA16NA03600G	Payne AC	16S 3T DG	Lite base pan and top edge dent	1	780.00
3934	PA16NA03600G	Payne AC	16S 3T DG	Dented grill very light coil fin damage	1	780.00
3921	PA16NW01800G	Payne AC	16S 1.5T DG	Grill slightly pushed in small fin dam	1	949.00
3910	PG8MAA066135	Payne Furnace	80 AFUE 4way	Top corner small tweek	1	555.00
3910	PH14NB04200G	Payne HP	14S 3.5T DG	Lite dent to base and top edge	1	1,196.00