

November 20, 2018

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

Branch	Model	Brand	Description		QTY	Price Each
3940	113AEA036000	Bryant AC	13S Legacy 3T P 460-3	Dent in top panel and side no box	1	699.00
3933	116BNA048000	Bryant AC	16S Legacy DG 4T	Minor cabinet damage	1	1,359.00
3921	126BNA018000	Bryant AC	16S Preferred 1.5T	Grill Bent/fin damage	1	1,219.00
3910	189BNV048000	Bryant AC	Evolution VS 4T	Grill dent bottom corner	1	1,999.00
3940	310AAV060155	Bryant Furnace	80% STD 4way Multi	Medium damage	1	699.00
3934	310AAV066135	Bryant Furnace	80% STD 4way multi	Dented side	1	450.00
3930	912SC60080S21	Bryant Furnace	92% SS GASF AF	Minor cabinet damage	1	949.00
3952	915SA60100S21	Bryant Furnace	95% SS	Medium damage	1	1,110.00
3940	986TB60080V21	Bryant Furnace	96% 2stage w/ECM	Dent in back/ scratches	1	990.00
3910	280ANV048000	Bryant HP	Evolution Inverter 4T	Grill dent bottom corner coil rub	1	3,849.00
3933	24ABB330A005	Carrier AC	13S Comfort P 2.5T 3 phase	Very minor cabinet dent installed	1	639.00
3930	24ABB336A005	Carrier AC	13S Comfort 3T 3phase	Sweated in	1	679.00
3910	24VNA948A003	Carrier AC	Infinity VS 4T	Medium damage	1	2,350.00
3910	CA13NA018BNG	Carrier AC	13S 1.5T DG	Base pan dent	2	829.00
3934	CA13NA0420NG	Carrier AC	13S 3.5T DG	Dented service panel	1	650.00
3930	CA13NA048BNG	Carrier AC	13S 4T DG	Minor cabinet damage	1	1,249.00
3934	CA13NA0600NG	Carrier AC	13S 5T	Dented corner and access panel door	1	749.00
3910	58CVA110---1--20	Carrier Furnace	80% Plus VS 2stg 4way MP	Lite cabinet tweek	1	889.00
3910	58STA110---1--16	Carrier Furnace	80% STD 4way multi	Lite cabinet tweek	1	475.00
3910	CH14NB01800G	Carrier HP	14S 1.5T DG	Lite pan dent	1	799.00
3930	CH14NB03000G	Carrier HP	14S 4T DG	Minor cabinet damage	1	810.00
3930	CH14NB03600G	Carrier HP	14S 3T DG	Bent bottom pan	1	625.00
3930	38GRQB18---3	DLS	27 Seer 18K CDU	Lite/med cabinet damage	1	679.00
3930	38MAQB09R--1	DLS	24S 9K 115V HP C DU	No box	1	325.00
3920	40MKB54F--3	DLS	54K 230V IDU under ceiling	Lite cabinet damage	2	625.00
3930	ECD-TC0407-DB	Economizer	R Dry Bulb CRECOMZR020A02	Bent metal	1	150.00
3930	ECD-TC0407-DB	Economizer	R Dry Bulb CRECOMZR020A02	Bent metal	1	150.00
3921	CNPVP1917ALA	Evap Coil	1.5T 17" P	Lite cabinet damage	1	200.00