

October 18, 2019

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

	Model		Brand	Description		QTY	Price Each
3910	CEV3614E32	2F	ADP Coil	3T 14" vertical coil w/o TXV	Light cabinet damage	1	199.00
3910	CEV6024E36	2F	ADP Coil	5T vertical w/o txv	Light cabinet damage	1	325.00
3910	113ANA0420N0	1C	Bryant AC	13S 3.5T	Top is slightly rolled over on one side	1	796.00
3933	113ANA0600N0	1C	Bryant AC	13S 5T	Light cabinet damage	1	899.00
3921	116BNA042000	1C	Bryant AC	16S 3.5T	Light cabinet damage	1	932.00
3921	180CNV024000	1C	Bryant AC	Evolution 20S VS 2T	Light cabinet damage	1	2,352.00
3930	180CNV024000	1C	Bryant AC	Evolution 20S VS 2T	Light cabinet damage	1	2,352.00
3920	189BNV036000	2C	Bryant AC	Evolution 19S 3T	Light/med cabinet damage	1	1,838.00
3930	189BNV036000	1C	Bryant AC	Evolution 19S 3T	Light cabinet damage	1	1,838.00
3910	315AAV036070	1C	Bryant Furnace	Plus 80% 2stg VS	Small dent bottom side	1	749.00
3910	880TA36070C14	2F	Bryant Furnace	80 VS 4way Combust Gas	Light cabinet damage	3	1,495.00
3933	912SD30040E14	1C	Bryant Furnace	92% 4way	Light cabinet damage	1	999.00
3920	915SA60100S21	2C	Bryant Furnace	95% SS	Light/med cabinet damage	1	719.00
3921	986TB66100V21	1C	Bryant Furnace	96% 2stg w/ECM	Light cabinet damage	1	1,579.00
3910	214DNA048000	FC	Bryant HP	14S 4T Legacy	Light dent at base pan no coil damage	1	1,120.00
3910	BH14NB03000G	1C	Bryant HP	14S 2.5T DG	Light cabinet damage	1	567.00
3920	24ABB336A005	2F	Carrier AC	13S Comfort 3T 3phase	Coil fins smashed on corner	1	843.00
3930	24ABB342A005	1W	Carrier AC	13S 3.5T 3phase	Light cabinet damage	1	1,007.00
3920	24VNA949A003	2C	Carrier AC	Infinity 19S 4T VS	Light/med cabinet damage	1	1,962.00
3910	CA13BA018BNG	2F	Carrier AC	13S 1.5T	Base pan bent up in front slight coil rub	1	485.00
3910	CA13NA024BNG	FC	Carrier AC	13S 2T DG	Lite pan damage	1	499.00
3910	CA13NA030BNG	FC	Carrier AC	13S 2.5T DG	Lite base pan and top edge dent	1	499.00
3910	CA13NA030BNG	2C	Carrier AC	13S 2.5T DG	Light/med cabinet	1	499.00

					damage		
3930	CA13NA0420NG	1C	Carrier AC	13S 3.5T DG	Light cabinet damage	1	675.00
3930	CA13NA0600NG	1C	Carrier AC	13S 5T DG	Light cabinet damage	1	912.00
3930	CA13NA0600NG	1W	Carrier AC	13S 5T DG	Light cabinet damage	1	912.00
3910	38MPRAQ24AA3	2F	Carrier DLS	HP 2T 208/230	Scratch and lite dent to side of cabinet	1	945.00
3920	59MN7B080C21--20	2C	Carrier Furnace	Infinity 4way MP	Light/med cabinet damage	1	1,949.00
3951	59SC5A100S21--20	2F	Carrier Furnace	95% SS	Light/med cabinet damage	1	899.00
3930	59TN6A060V17--14	1C	Carrier Furnace	96% 2stg	Light cabinet damage	1	985.00
3910	59TP6A040E14--10	1C	Carrier Furnace	96% AFUE 2S/PWM	Light cabinet damage	1	606.00
3920	59TP6B040V17--12	2C	Carrier Furnace	96% AFUE 2S/PWM	Light/med cabinet damage	1	899.00
3910	25HBC524A003	1C	Carrier HP	15S 2T	Light cabinet damage	1	774.00
3934	25HBC524A003	2C	Carrier HP	15S Comfort 2T DG	Top damage	1	774.00
3910	25HCE430A003	2C	Carrier HP	14S 2.5T	Light/med cabinet damage	1	1,349.00
3910	CH14NB02400G	1C	Carrier HP	14S 2T DG	Light cabinet damage	1	552.00
3930	CH14NB03000G	1W	Carrier HP	14S 2.5T DG	Light cabinet damage	2	624.00
3910	CH14NB04800G	FC	Carrier HP	14S 4T DG	Small pan dent, ligh coil sub	1	749.00
3930	38MAQB24R--3	1C	DLS	24S 24K 230V HP CDU	Light cabinet damage	1	1,199.00
3910	38MBRQ36A--3	1C	DLS	36K 230V HP CDU	Dirty and scratches no damage	3	1,899.00
3921	38MBRQ36A--3	1C	DLS	36K 230V HP CDU	Light cabinet damage	1	1,899.00
3910	38MHRBC18AA3	2F	DLS	CLG Only CU 18K	Light/med cabinet damage	1	649.00
3930	38MHRBQ12AA3	1C	DLS	12K 230V HP CDU	Light cabinet damage	1	489.00
3910	CAPMP6024ALA	1C	Evap Coil	5T 24"	Pinched corner	1	244.00
3934	CEH3614D12	3C	Evap Coil	3T 14" ADP	Side damage cab only	1	205.00
3934	CNPHP3617ALA	2C	Evap Coil	3T 17" horizontal	Light/med cabinet damage	1	170.00
3940	CNPHP3617ALA	2C	Evap Coil	3T 17" horizontal	Light/med cabinet damage	1	170.00
3920	CNPHP3617ALA	2C	Evap Coil	3T 17" horizontal	Light/med cabinet damage	1	170.00
3910	CNPHP4821ALA	1C	Evap Coil	4T 21" horizontal	Light cabinet damage	1	200.00
3910	CNPHP4821ALA	2C	Evap Coil	4T 21" horizontal	Light/med cabinet damage	1	200.00
3940	CNPHP4821ALA	2C	Evap Coil	4T 21" horizontal	Light/med cabinet damage	1	200.00
3940	CNPHP6024ALA	2C	Evap Coil	5T 24" horizontal	Light/med cabinet damage	1	224.00
3920	CNPVP3117ALA	2C	Evap Coil	2.5T 17"	Light cabinet damage	2	210.00
3920	CNPVP3717ALA	2C	Evap Coil	3T 17" horizontal	Light cabinet damage	1	210.00
3910	CNPVP4324ALA	1C	Evap Coil	3.5T 24"	Light cabinet damage	1	255.00
3920	CNPVP4324ALA	1C	Evap Coil	3.5T 24"	Light cabinet damage	1	255.00
3934	CNRVU4824ALA	2C	Evap Coil	R22 4T 24"	Light/med cabinet damage	1	229.00

3910	FB4CNP060L00	FC	Fan Coil	5T AI	Light cabinet damage	1	523.00
3910	FMA4X1800AL	2C	Fan Coil	AI w/ECM 1.5T	Bottom dent back med	1	368.00
3910	GC036VTLCDET1XX1	2C	GEO	3T WHSP w/hwg	MAKE US AN OFFER	1	
3910	GC036VTLNDET1XX1	2C	GEO	3T WHSP CN w/hwg	MAKE US AN OFFER	1	
3910	PA13NA018BNG	FC	Payne AC	13S 1.5T DG	Dents to base pan and top	1	477.00
3921	PA16NW01800G	2F	Payne AC	16S 1.5T DG	Grill slightly pushed in small fin dam	1	625.00
3910	PH14NB04200G	FC	Payne HP	14S 3.5T DG	Lite dent to base and top edge	1	980.00