



SCHEMATIC DIAGRAM



| JUMPER SETTING | INPUT            |
|----------------|------------------|
|                | 0 - 135 $\Omega$ |
|                | 4 - 20 mA        |
|                | 0 - 10 VDC       |



|     |     |   |     |   |   |                                                          |
|-----|-----|---|-----|---|---|----------------------------------------------------------|
| THS | XXX | X | XXX | X | X | TRANSFORMER: (N) NONE REQUIRED; (T) TRANSFORMER REQUIRED |
|     |     |   |     |   |   | STYLE: (O) OPEN TYPE; (B) BOX TYPE                       |
|     |     |   |     |   |   | SCR VOLTAGE: 120V - 600V MAXIMUM                         |
|     |     |   |     |   |   | VOLTAGE PHASE: (1) SINGLE PHASE; (3) THREE PHASE         |
|     |     |   |     |   |   | AMPERAGE: MAXIMUM LOAD AMPERAGE APPLIED TO SCR           |
|     |     |   |     |   |   | MODEL LINE: THS - REMOTE SCR                             |

TITLE/TITRE

THS-30-3-XXX-O-N



THERMOLEC

LTEE LTD

MONTREAL - CANADA

DRAWING NO. THS-30-3-XXX-O-N

DATE

PER