



comfort | excellence
Comfort Products Distributing

Comfort Products Distributing
13202 I Street
Omaha, NE 68137
Ph: 402-334-7777 or 800-779-8299
comfortproducts.com

February 7, 2019

At times Comfort Products Distributing receives product that has been slightly mishandled. Please take advantage of these items at a reduced cost. All equipment will come with full factory warranty. Please call or email Beckie Wiebelhaus for more details 402-951-3213 rwiebelhaus@comfortproducts.com

Branch	Model		Brand	Description		QTY	Price Each
3921	126BNA018000	DF	Bryant AC	16S Preferred 1.5T	Grill Bent/fin damage	1	600.00
3910	189BNV048000	DC	Bryant AC	Evolution VS 4T	Grill dent rub to coil	1	1,299.00
3910	280ANV048000	DC	Bryant HP	Evolution Inverter 4T	Grill dent bottom corner coil rub	1	2,999.00
3930	24ABB336A005	2C	Carrier AC	13S Comfort 3T 3phase	Sweated in	1	499.00
3951	24ABC636A003	2F	Carrier AC	16S 3T	Lite cabinet damage	1	949.00
3910	CA13NA018BNG	2F	Carrier AC	13S 1.5T DG	Base pan dent	1	799.00
3934	CA13NA0420NG	2C	Carrier AC	13S 3.5T DG	Dented service panel	1	599.00
3930	CA13NA048BNG	1C	Carrier AC	13S 4T DG	Minor cabinet damage	1	900.00
3934	CA13NA0600NG	2C	Carrier AC	13S 5T	Dented corner and access panel door	1	699.00
3934	CH14NB02400G	2C	Carrier HP	14S 2T DG	Lite cabinet damage	1	849.00
3930	CH14NB03000G	1C	Carrier HP	14S 2.5T DG	Minor cabinet damage	1	799.00
3910	CH14NB06000G	FC	Carrier HP	14S 5T DG	Base pan damage	1	1,450.00
3910	CNPVP1814ALA	FC	Evap Coil	1.5T 14"	Light cabinet	2	185.00
3921	CNPVP1917ALA	DF	Evap Coil	1.5T 17" P	Lite cabinet damage	1	200.00
3921	CNPVP2417ALA	2W	Evap Coil	2T 17"	side dent to caninet116bna036000	1	195.00
3910	CNPVP4217ALA	1c	Evap Coil	3.5T 17"	Light cabinet	1	210.00
3920	CNPVP4221ALA	2W	Evap Coil	3.5T 21"	Lite cabinet damage	1	210.00
3934	CNPVP6024ALA	2C	Evap Coil	5T Al 24"	Lite cabinet damage	1	220.00
3934	FB4CNP030L00	2C	Fan Coil	2.5T AL	Lite cabinet damage	1	499.00
3930	FFMAN031T00	1C	Fan Coil	TP 2.5T	Lite cabinet damage	1	500.00
3921	PA13NA024BNG	1W	Payne AC	13S 2T DG	Lite cabinet damage	1	589.00
3930	PA13NA0420NG	1C	Payne AC	13S 3.5T DG	Bent bottom pan	1	499.00
3921	PA16NW01800G	2F	Payne AC	16S 1.5T DG	Grill slightly pushed in small fin dam	1	949.00